

Product Safety Recall

RZR Pro XP (2-Seat only) Model Year 2021-2022



Defect: Fuel may leak from the fuel pump joint.

Hazard: If fuel leaks near an ignition source it may cause a fire or explosion, increasing the risk of serious injury or death to vehicle occupants.

What to do: Consumers should not operate their vehicle.

Polaris will notify consumers once the recall repair procedure has been finalised.

Consumers will then be able to contact their preferred Polaris dealer and arrange a time to book their vehicle in for repairs.

To find a local dealer, visit www.polarisaustralia.com/find-a-dealer/list-view/ or call 1300 654 142.

For further information: For further information, consumers should contact Polaris Customer Service on 03 9394 5620 or at www.polarisaustralia.com

**See productsafety.gov.au for
Australian product recall information**