

ELECTRICAL SAFETY RECALL

Electric Recliners and Sofas with Cupholders in the armrests



MODEL: E1213

IDENTIFICATION: Electric recliners and sofas with cupholders in the armrests.

Models:

1. MACPHERSON / JULIET 3ERER
2. MACPHERSON / JULIET 2ERER
3. MACPHERSON / JULIET 1ER
4. PARAMOUNT 3ERER
5. PARAMOUNT 2ERER
6. PARAMOUNT 1ER
7. JORDAN 2ERER

The sofas and recliners may be leather or fabric.

DEFECT: During use, the electrical components in the cupholder may overheat.

HAZARD: Risk of fire or burns causing serious injury or death. A defect has occurred causing a fire resulting in injury and property damage.

ACTION REQUIRED: Consumers should check their recliner/sofa to see if it is one of the affected models and if so immediately turn off the power and unplug the power cord from the wall outlet.

Consumers should then contact Dixie Cummings Enterprises Pty Ltd:

- for instructions about how to disconnect the cupholder safely
- to ask for assistance, if needed
- to arrange for the replacement of the cupholder and insertion of a dummy plug

For further information and assistance

please contact Dixie Cummings Enterprises Pty Ltd by phone on 03 97622988, email at aftersalessupport@dixiecummings.com.au or via the website at <https://www.dixiecummings.com.au/contact-us>

See www.productsafety.gov.au for Australian product recall information