

# Product Safety Recall

## Aqualung Australia - Aqualung i330R Dive Computer

### Product Description

Aqualung i330R Dive Computers and Consoles produced and sold in 2021 and 2022 with operating firmware versions R1.001, R1.002, or R1.003

### Serial Numbers Affected

GD-001004 to GD-015302  
GM-001000 to GM-003305  
GM-001011 to GM-001269

### What Are The Defects?

The Dive Computer does not automatically adjust the pressure level when diving at 900m (3000ft) altitude or higher, leading to miscalculation of the remaining dive time and ascent procedure

### What Are The Hazards?

A diver who relies on the computer may exceed their no-decompression limit, leading to decompression sickness which can result in injury, serious illness, or death



### What Should Consumers Do?

Consumers should immediately stop using the i330R dive computer. Consumers should take the dive computer to their place of purchase or any authorised Aqualung dealer to receive a free firmware upgrade. After the update the firmware will be R1.0004 or later

You can contact Aqualung by email [salesaqz@aqualung.com](mailto:salesaqz@aqualung.com)

You can go to [aqualung.com.au/pages/store-locator](https://aqualung.com.au/pages/store-locator) to find your nearest authorised dealer

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information