

Product Safety Recall

Bolzen Commando 4822D



Dual motor electric scooter sold at various retailers between April 2022 and January 2023.

Defect: The folding mechanism pivot bolt may fail, this can lead to excessive play in the steering and handlebars. The handlebars may also partly detach from the deck.

Hazard: If the bolt fails there is an increased risk of a fall or an accident resulting in serious injury or death.

What to do: Consumers should immediately stop riding the scooter and contact the place of purchase to arrange a free repair.

Contact details: For more information contact Bolzen Pty Ltd on info@bolzen.com or by phone on 02 7258 3944.

See productsafety.gov.au for
Australian product recall information