



Product Safety Recall



Do you own this product?

Dometic Marine — Dometic Marine steering cable for Malibu Response, Malibu Wakesetter and Axis boats

A steering cable installed in the following boat models with mechanical steering systems.

- Malibu Response
- Malibu Wakesetter – All Models
- Axis – All Models

Dates sold: 25 August 2022 – 14 March 2023



Why the product is recalled: The steering cable clamp block can release under normal use resulting in loss of steering.

Hazard: Risk of serious injury or death to boat occupants or bystanders if the steering cable clamp block fails and leads to a loss of steering control.



1. Consumers should check if their boat HIN is included in the supplied list. Affected consumers should immediately stop using their boat and contact Malibu and Axis dealers to arrange a free of charge repair.
2. To contact your closest Malibu and Axis Boat Dealers in Australia please visit <https://www.malibuboats.com.au/malibu-boats-specialists>



For more information contact Malibu Boats Australia on 02 6040 1174, email recalls@malibuboats.com.au, or via the online contact form <https://www.malibuboats.com.au/malibu-boats-specialists#contactus>



Purchased from Malibu and Axis boat dealers nationally.

PRA 2023/19776

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information