



# Product Safety Recall

## TDJ Australia — Aerpro lights for vehicles



Various models of vehicle lights affected.

9x LR1130 button batteries located in the 'TRY ME' button of the product packaging.

Affected part numbers:

SMD83R	SMD92R	SMD98B	T106A	T109TG
SMD83W	SMD94G	SMD98W	T106B	SMD16R
SMD85W	SMD94R	T102A	T109B	SMD81G
SMD91G	SMD96B	T104B	T109G	
SMD91R	SMD97B	T104Y	T109TB	

Part numbers can be found on the packaging of the product. See [productsafety.gov.au](https://www.productsafety.gov.au) for a list of affected models, part numbers and photographs.

Dates sold: 1 June 2022 – 26 September 2023



**Why the product is recalled:** The product does not comply with the [mandatory standards for products containing button/coin batteries](#). The button/coin batteries are not adequately secured and are accessible by young children. The product does not include the required warning information.

**Hazard:** There is a risk of choking or serious injury if young children gain access to the button/coin batteries and swallow or place them inside their body. Consumers may be unaware that the product contains button batteries.



Consumers should ensure the product packaging is kept out of reach of children and disposed of safely.

Consumers can return the uninstalled product to the place of purchase or to TDJ Australia Pty Ltd for a full refund.



Contact TDJ for a reply-paid label via email [Customerservice@tdj.com.au](mailto:Customerservice@tdj.com.au) or phone 03 8587 8888 (9:00 am – 5:00 pm, Monday – Friday).

For more advice and options on how to safely dispose button batteries check [Recycle Mate](#) or [B-Cycle](#).



Purchased from: Auto parts and accessories stores.

PRA 2024/20030

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information